

DEPARTURE ROUTE DESCRIPTON

TAKEOFF RUNWAY 10: Climb on heading 096° to 2000 then as assigned for RADAR vectors to cross FEMTO at or above 12000 thence....

TAKEOFF RUNWAY 18: Climb on heading 185° or as assigned for RADAR vectors to cross FEMTO at or above 12000 thence. . . .

TAKEOFF RUNWAY 28: Climb on heading 276° or as assigned for RADAR vectors to cross FEMTO at or above 12000 thence. . . .

TAKEOFF RUNWAY 36: Climb on heading 005° or as assigned for RADAR vectors to cross FEMTO at or above 12000 thence. . . .

. . . on track 347° to VACAY, then on assigned transition, maintain ATC assigned altitude, expect clearance to filed altitude 10 minutes after departure.

STYMY TRANSITION (VACAY1.STYMY)
WAPOM TRANSITION (VACAY1.WAPOM)